Experian AutoCheck Report

Report run: 10/29/2026 08:11:21 EDT

2023 Volkswagen ID.4 Pro

SUV 4D (Electric 295 295)

VIN:	1V2DNPE83PC055897
Class:	CUV - Midsize
Country of Assembly:	United States
Vehicle Age:	3 year(s)
Estimated In Service:	12/12/2023
Last Reported Odometer:	18,845 (10/09/2026)

Owners - 2

Vehicle Usage

Fleet, Lease

90 **90** 95

AutoCheck Score

Similar vehicles usually range between **90 and 95**

Vehicle History at a Glance

State Title Brand

Clean

Auction Brand / Issues

No Issue

Accident / Damage

No Accidents or Damage Reported

No Issue

Open Recall Check

2 Open Recall(s)

Insurance Loss / Transfer

No Issue

Odometer Check

Last reported odometer: **18,845 (10/09/2026)**

No Issue

Certified Pre-Owned

No CPO Info Available

Service / Repair

5 Service Record(s) Reported

No Issue

Additional History

Lien Reported


Events Reported

This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. **Terms & Conditions**

Learn More

Accident & Damage



Airbag Deployed | Structural Damage | Overturned | No Damage

Your Vehicle Checks Out

There were no accidents or damage events disclosed to Experian AutoCheck for this vehicle. Since not all damage-related events are reported to Experian AutoCheck, an inspection may provide added confidence in the vehicle's condition before purchase.

Open Recall Check

Information Reported: AutoCheck found 2 open recall(s).

It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Service bulletins if available are not part of open recalls and can be found in the vehicle history details.

Recall Date	Recall Type	NHTSA / OEM Recall No.	Campaign Description
09/06/2024	Safety	N/A / 57J9	Safety Recall: DOOR HANDLES Status: Remedy Unknown
01/23/2026	Unspecified	N/A / 93EA	HV BATTERY Status: Remedy Unknown

More information including remedy or risk factors. Locate your nearest authorized VW Dealer to schedule repair.

Recommended Maintenance

OEM Recommended Maintenance Schedule

Based on your vehicle's last reported mileage, these are the most recent and upcoming recommended maintenance intervals from your vehicle's manufacturer.

OEM Recommended Services

10000 Mile Service

- Battery (12V) and HighVoltage Battery, Checking with Vehicle Diagnostic Tester
- Service Interval Display, Resetting
- Tires, Checking Condition and Wear Pattern; Tread Depth, Entering
- Use the Vehicle Diagnostic Tester to Check for DTCs

20000 Mile Service

Not Yet Due

- Automatic Headlamp Control, Checking Function
- Ball Joints, Axle Bearings, Coupling Rod and Stabilizer Bar Rubber Bushings, Visually Inspecting for Damage
- Battery (12V) and HighVoltage Battery, Checking with Vehicle Diagnostic Tester
- Body Interior and Exterior, Visually Inspecting for CorrosionBrake Fluid Level, Checking Depending on Brake Pad Wear
- Brake System and Shock Absorbers, Visually Inspecting for Leaks and Damage.
- Charging Cable, Checking Presence and Condition. Only applies to BEV and PHEV
- Cooling System, Checking Freeze Protection and Coolant Level
- Engine and Components in Engine Compartment (from Below), Visually Inspecting for Leaks and Damage
- Engine and Engine Compartment Components, Visually Inspecting for Leaks and Damage from Above
- Every 40,000 miles or 2 years, whichever occurs first
- front and rear Brake Pad Thickness and Brake Rotor Condition, Checking
- front and rear Coil Springs and Stop Buffers, Visually Inspecting for Damage
- front Lighting, Checking Function

30000 Mile Service

Not Yet Due

- Battery (12V) and HighVoltage Battery, Checking with Vehicle Diagnostic Tester
- Service Interval Display, Resetting
- Tires, Checking Condition and Wear Pattern; Tread Depth, Entering
- Use the Vehicle Diagnostic Tester to Check for DTCs

- Guided Fault Finding Use the Vehicle Diagnostic Tester to Check for DTCs
- Headlamps, Checking and Adjusting if Necessary
- Headlamp Washer System, Checking Function
- HighVoltage Battery Charge Level, Checking and Charging if Necessary. Only applies to BEV
- HighVoltage Battery, Charging. Only applies to BEV
- HighVoltage Charging Sockets in Radiator Grille or Fuel Filler Cap. Visual Inspection Contamination and Damage, Performing. Only applies to BEV
- HighVoltage Components and HighVoltage Cables, Visually Inspecting for Damage, Correct Wire Routing and Attachment. Only applies to BEV
- Horn, Checking Function
- Interior Lamps in Headliner, Luggage Compartment and Glove Compartment Lamps, Checking Function
- Perform Minor Maintenance
- rear Lamps, Checking Function
- Removable Trailer Hitch, Checking. if equipped
- Road Test, Performing
- Service Interval Display, Resetting
- Stationary Cornering Lamp, Checking Function
- Tie Rods, Checking Play, Attachment and Ball Joint Boots
- Tire Pressure, Checking

- Tire Pressure Monitoring System, Calibrating to Tire Pressure Adjustment
- Tire Repair Kit, Checking for Damage and Use
- Tires, Checking Condition and Wear Pattern; Tread Depth, Entering
- Transmission, Final Drive and CV Boots, Checking for Leaks and Damage
- Underbody, Visually Inspecting Underbody Protection, Underbody Trim Panels, Wire Routing and Plugs for Damage
- Warning Label, Checking Presence. Only applies to BEV
- Windshield, Visually Inspecting for Damage
- Windshield Wiper/Washer System, Checking Function, Spray Nozzle Adjustment and for Damage, and Adjusting if Necessary
- Wiper Blades, Bringing into Service Position, Checking for Damage and Checking Park Position

Odometer Check

Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

State Title Odometer Check

No issues reported

Auction Odometer Check

No issues reported

Odometer Calculation Check

No issues reported

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.

2023 - Vehicle Prep and Other Pre-Titling Events

Location: MISSOULA, MT **Preparation Date:** 12/2023

Event Date	Location	Odometer	Data Source	Details
12/12/2023	MISSOULA, MT	10	Dealer Listing	Vehicle Listed for Sale
01/02/2024	MISSOULA, MT		Service Record	Vehicle Serviced or Inspected
04/22/2024	MISSOULA, MT	10	Service Record	Vehicle Serviced or Inspected
06/10/2024	MISSOULA, MT	441	Service Record	Vehicle Serviced or Inspected

2024 - Owner 1

Location: MT **Owned From:** 07/2024 **Usage:** Lease

Event Date	Location	Odometer	Data Source	Details
07/01/2024	MISSOULA, MT		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
07/12/2024	MT		Motor Vehicle Dept.	Title(Title #:AA7627549) (Leased Vehicle) (Lien Reported)
08/09/2024	MT		Motor Vehicle Dept.	Title(Title #:AA7627549) (Leased Vehicle) (Lien Reported)
08/19/2024	MISSOULA, MT	2,804	Service Record	Vehicle Serviced or Inspected
09/06/2024			Manufacturer	Manufacturer Recall Mfr. Recall 57J9 Safety Recall: DOOR HANDLES LOCATE YOUR NEAREST AUTHORIZED **VW DEALER** TO SCHEDULE REPAIR. Status: Remedy Unknown
12/10/2024	MISSOULA, MT	5,298	Service Record	Vehicle Serviced or Inspected
07/09/2025	LEBANON, PA	9,712	Motor Vehicle Dept.	Title(Title #:88774273) (Leased Vehicle)

2025 - Owner 2

Location: PA **Owned From:** 08/2025 **Usage:** Fleet, Lease

Event Date	Location	Odometer	Data Source	Details
08/06/2025	PA	9,713	Motor Vehicle Dept.	Title(Title #:88774273) (Leased Vehicle) Registration Event/Renewal(Leased Vehicle)
01/23/2026			Manufacturer	

				Manufacturer Recall Mfr. Recall 93EA HV BATTERY LOCATE YOUR NEAREST AUTHORIZED **VW DEALER** TO SCHEDULE REPAIR. Status: Remedy Unknown
10/05/2026	PA	18,845	Auto Auction	Auction Announced as Fleet/Lease(COLOR REPORTED AS GREY)
10/09/2026	PA	18,845	Auto Auction	Reported at Auto Auction

Unreported Event Dates

The following events have been reported to AutoCheck without a specified date.

Event Date	Location	Odometer	Data Source	Details
Unreported			Independent Source	Vehicle Manufactured and Shipped to Dealer

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to **AutoCheck Terms and Conditions**. If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (1V2DNPE83PC055897) qualifies for **AutoCheck Buyback Protection.** If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbpterms or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.

