Experian AutoCheck Report

Report run: 10/21/2026 07:40:32 EDT

2023 Volkswagen Atlas V6 SE 4Motion

SUV 4D (3.6L V6 DI Gasoline)

VIN:	1V2KR2CA4PC545074
Class:	CUV - Large
Country of Assembly:	United States
Vehicle Age:	3 year(s)
Estimated In Service:	06/08/2023
Last Reported Odometer:	37,002 (10/06/2026)

One Owner AutoCheck

Vehicle Usage

Fleet, Lease

89 **90** 94

AutoCheck Score

Similar vehicles usually range between **89 and 94**

Vehicle History at a Glance

State Title Brand

Clean

Auction Brand / Issues

No Issue

Accident / Damage

No Accidents or Damage Reported

No Issue

Open Recall Check

1 Open Recall(s)

Insurance Loss / Transfer

No Issue

Odometer Check

Last reported odometer: **37,002 (10/06/2026)**

No Issue

Certified Pre-Owned

No CPO Info Available

Service / Repair

No Issue

Additional History

No Issues Reported


1 Year AutoCheck BUYBACK Protection

This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. **Terms & Conditions**

Learn More

Accident & Damage



Airbag Deployed | Structural Damage | Overturned | No Damage

Your Vehicle Checks Out

There were no accidents or damage events disclosed to Experian AutoCheck for this vehicle. Since not all damage-related events are reported to Experian AutoCheck, an inspection may provide added confidence in the vehicle's condition before purchase.

Open Recall Check

Information Reported: AutoCheck found 1 open recall(s).

It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Service bulletins if available are not part of open recalls and can be found in the vehicle history details.

Recall Date	Recall Type	NHTSA / OEM Recall No.	Campaign Description
06/25/2024	Safety	N/A / 69PZ	Safety Recall: PODS Status: Remedy Unknown

More information including remedy or risk factors. Locate your nearest authorized VW Dealer to schedule repair.

Recommended Maintenance

OEM Recommended Maintenance Schedule

Based on your vehicle's last reported mileage, these are the most recent and upcoming recommended maintenance intervals from your vehicle's manufacturer.

OEM Recommended Services

- 30000 Mile Service
- 40000 Mile Service — Not Yet Due
- 50000 Mile Service — Not Yet Due

- Engine Oil, Draining and Replacing Oil Filter
- Engine Oil, Filling
- front and rear Brake Pad Thickness and Brake Rotor Condition, Checking
- Service Interval Display, Resetting
- Tires Rotate front to rear 2015> Canada

- Automatic Headlamp Control, Checking Function
- Ball Joints, Axle Bearings, Coupling Rod and Stabilizer Bar Rubber Bushings, Visually Inspecting for Damage
- Battery and Auxiliary Battery, Checking with Battery Tester if Necessary
- Body Interior and Exterior, Visually Inspecting for Corrosion
- Brake Fluid Level, Checking Depending on Brake Pad Wear
- Brake System and Shock Absorbers, Visually Inspecting for Leaks and Damage.
- Cooling System, Checking Freeze Protection and Coolant Level
- Engine and Components in Engine Compartment (from Below), Visually Inspecting for Leaks and Damage
- Engine and Engine Compartment Components (from Above), Visually Inspecting for Leaks and Damage
- Engine Oil Level, Checking
- Every 20,000 miles or 2 years, whichever occurs first
- Every 2 years or every 40,000 miles, whichever occurs first
- Exhaust System, Visually Inspecting for Leaks, Attachment and Damage
- front and rear Brake Pad Thickness and Brake Rotor Condition, Checking
- front and rear Coil Springs and Stop Buffers, Visually Inspecting for Damage

- Engine Oil, Draining and Replacing Oil Filter
- Engine Oil, Filling
- front and rear Brake Pad Thickness and Brake Rotor Condition, Checking
- Service Interval Display, Resetting
- Tires Rotate front to rear 2015> Canada

- front Lighting, Checking Function
- Headlamps, Checking and Adjusting if Necessary
- Headlamp Washer System, Checking Function
- Horn, Checking Function
- Interior Lamps in Headliner, Luggage Compartment and Glove Compartment Lamps, Checking Function
- Perform Minor Maintenance
- rear Lamps, Checking Function
- Removable Trailer Hitch, Checking. if equipped
- Ribbed Belt, Checking Condition
- Road Test, Performing
- Service Interval Display, Resetting
- Sliding Sunroof, Checking Function, Cleaning Guide Rails, Lubricating with Special Lubricant
- Stationary Cornering Lamp, Checking Function
- Tire Pressure, Checking
- Tire Pressure Monitoring System, Calibrating to Tire Pressure Adjustment
- Tire Repair Kit, Checking for Damage and Use
- Tires, Checking Condition and Wear Pattern; Tread Depth, Entering
- Tires Rotate front to rear 2015> Canada
- Torque splitter: Read out Oil deterioration of the left and right side using the Vehicle Diagnostic Tester (if equipped)
- Transmission, Final Drive and CV Boots, Checking for Leaks and Damage

- Underbody, Visually Inspecting Underbody Protection, Underbody Trim Panels, Wire Routing and Plugs for Damage
- Windshield, Visually Inspecting for Damage
- Windshield Wiper/Washer System, Checking Freeze Protection and Filling Fluid
- Windshield Wiper/Washer System, Checking Function, Spray Nozzle Adjustment and for Damage, and Adjusting if Necessary
- Wiper Blades, Bringing into Service Position, Checking for Damage and Checking Park Position

Odometer Check

Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

State Title Odometer Check

No issues reported

Auction Odometer Check

No issues reported

Odometer Calculation Check

No issues reported

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.
Vehicle: 2023 Volkswagen Atlas V6 SE 4Motion (1V2KR2CA4PC545074) **Report Run Date:** 10/21/2026 07:40:32 EDT

2023 - Vehicle Prep and Other Pre-Titling Events

Location: ONLINE DEALER **Preparation Date:** 06/2023

Event Date	Location	Odometer	Data Source	Details
06/08/2023	ONLINE DEALER	4	Dealer Listing	Vehicle Listed for Sale

2023 - Owner 1

Location: NY | **Owned From:** 06/2023 | **Usage:** Fleet, Lease

Event Date	Location	Odometer	Data Source	Details
06/25/2023	NY		Independent Source	Vehicle Manufactured and Shipped to Dealer
06/25/2023	EAST NORTHPORT, NY		Motor Vehicle Dept.	Registration Event/Renewal
06/25/2023	NY	22	Motor Vehicle Dept.	Emission Inspection Passed Safety Inspection
07/10/2023	NY		Motor Vehicle Dept.	Title(Leased Vehicle)
07/10/2023	NY		Motor Vehicle Dept.	Title(Leased Vehicle)
06/25/2024			Manufacturer	Manufacturer Recall Mfr. Recall 69PZ Safety Recall: PODS LOCATE YOUR NEAREST AUTHORIZED **VW DEALER** TO SCHEDULE REPAIR. Status: Remedy Unknown
07/03/2024	NY	12,324	Motor Vehicle Dept.	Emission Inspection Passed Safety Inspection
06/25/2025	EAST NORTHPORT, NY		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
09/21/2026	EASTERN REGION	37,002	Auto Auction	Auction Announced as Fleet/Lease(COLOR REPORTED AS GREY)
09/24/2026	EASTERN REGION	37,002	Auto Auction	Reported at Auto Auction
10/06/2026	EPHRATA, PA	37,002	Motor Vehicle Dept.	Title(Title #:90491239) (Leased Vehicle)

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to **AutoCheck Terms and Conditions**. If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (1V2KR2CA4PC545074) qualifies for **AutoCheck Buyback Protection.** If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbpterms or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.


experian