Experian AutoCheck Report

Report run: 11/04/2026 20:14:32 EST

2024 Audi Q8 Sportback e-tron quattro Prestige S-Line

SUV 4D (Electric 402 402)

VIN:	WA1DAAGE9RB017929
Class:	CUV - Compact Luxury
Country of Assembly:	Germany
Vehicle Age:	2 year(s)
Estimated In Service:	08/11/2023
Last Reported Odometer:	22,105 (10/20/2026)

One Owner AutoCheck

Vehicle Usage

Lease

89 **92** 94

AutoCheck Score

Similar vehicles usually range between **89 and 94**

Vehicle History at a Glance

State Title Brand

✓ Clean

Auction Brand / Issues

✓ No Issue

Accident / Damage

No Accidents or Damage Reported

✓ No Issue

Open Recall Check

! 1 Open Recall(s)

Insurance Loss / Transfer

✓ No Issue

Odometer Check

Last reported odometer: **22,105 (10/20/2026)**

✓ No Issue

Certified Pre-Owned

No CPO Info Available

Service / Repair
5 Service Record(s) Reported

No Issue

Additional History

No Issues Reported


1 Year AutoCheck BUYBACK Protection

This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. Terms & Conditions

Learn More

Accident & Damage



Airbag Deployed | Structural Damage | Overturned | No Damage

Your Vehicle Checks Out

There were no accidents or damage events disclosed to Experian AutoCheck for this vehicle. Since not all damage-related events are reported to Experian AutoCheck, an inspection may provide added confidence in the vehicle's condition before purchase.

Open Recall Check

Information Reported: AutoCheck found 1 open recall(s).

It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Service bulletins if available are not part of open recalls and can be found in the vehicle history details.

Recall Date	Recall Type	NHTSA / OEM Recall No.	Campaign Description
12/19/2023	Safety	N/A / 93U6	Safety Recall: CHARGING CABLE REPLACEMENT Status: Remedy Unknown

More information including remedy or risk factors. Locate your nearest authorized Audi Dealer to schedule repair.

Recommended Maintenance

OEM Recommended Maintenance Schedule

Based on your vehicle's last reported mileage, these are the most recent and upcoming recommended maintenance intervals from your vehicle's manufacturer.

OEM Recommended Services

20000 Mile Service

- Axle drive, front - drain coolant (with small cover removed)
- Axle drive, rear - drain coolant (with small cover removed) (SQ8 e-tron Only)
- Body/chassis - Visually inspect for possible paint damage and corrosion, from the inside and outside, with the doors as well as hood and trunk lids open
- Brake system - Check for damage and leaks, condition of brake hoses and the presence of the bleeder caps; Check the thickness of the brake pads
- Charging cable - Check for damage (if present in vehicle during inspection)
- Charging socket - Check for contamination and damage
- Connected box / OCU battery (for Audi Connected Services) - Check state health with Vehicle Diagnostic Tester in Guided Functions
- Door hinge (including door stay) and door latch - Lubricate
- Every 20,000 miles or 2 years, whichever occurs first
- Exterior lighting - Check front and rear lights, turn signals, cornering lights, reverse lights, license plate lights, and hazard warning lights

30000 Mile Service

Not Yet Due

- Brake system - Check the thickness of the brake pads
- Connected box battery - Check state of health with Vehicle Diagnostic Tester in Guided Functions
- First aid kit - Check and enter expiration date
- Front and rear axle /suspension components - Check dust seals on ball joints and tie rod ends; check for excessive play
- Instrument cluster - Check warning and indicator lights
- Multi-point inspection - Complete (USA Only)
- Service reminder indicator display - Reset display
- Space saver spare wheel and tire - Check condition and tire inflation pressure, adjust if necessary (if equipped)
- Tire repair kit - Check and record the completeness and expiration date (if equipped)
- Tires - Check condition and tire tread wear; Check and record the tread depth
- Tires - Check tire inflation pressure and adjust if necessary
- Wiper blades - Check condition and replace if necessary

40000 Mile Service

Not Yet Due

- Axle drive, front - drain coolant (with small cover removed)
- Axle drive, rear - drain coolant (with small cover removed) (SQ8 e-tron Only)
- Body/chassis - Visually inspect for possible paint damage and corrosion, from the inside and outside, with the doors as well as hood and trunk lids open
- Brake system - Check for damage and leaks, condition of brake hoses and the presence of the bleeder caps; Check the thickness of the brake pads
- Charging cable - Check for damage (if present in vehicle during inspection)
- Charging socket - Check for contamination and damage
- Connected box / OCU battery (for Audi Connected Services) - Check state health with Vehicle Diagnostic Tester in Guided Functions
- Door hinge (including door stay) and door latch - Lubricate
- Every 20,000 miles or 2 years, whichever occurs first
- Exterior lighting - Check front and rear lights, turn signals, cornering lights, reverse lights, license plate lights, and hazard warning lights

- First aid kit (if equipped) - Check and enter expiration date YYYY /MM _____
- Headlights - Check adjustment
- High voltage cooling system - Check coolant level according to ElsaPro
- High voltage safety instruction labels - Check safety instruction labels for legibility
- High voltage system components - Check for damage and leaks; check cables and insulation for damage and proper mounting
- High voltage system maintenance connector- Check for damages (deformation and scratches) and connector cleanliness
- Horn - Check function
- Instrument cluster - Check warning and indicator lights
- Interior lights - Check all interior lights, trunk lights and glove box compartment illumination
- Motor compartment - Check transmission, final drive, and steering for leaks and damage (including visible HV components with front noise insulation removed)
- Multi-point inspection - Complete (USA only)
- Parking brake actuator - Check activating range with Vehicle Diagnostic Tester
- Plenum chamber and water drain valves - Check for dirt. NOTE: Time spent cleaning of item is a separate charge for service time.
- Road test - Perform

- First aid kit (if equipped) - Check and enter expiration date YYYY /MM _____
- Headlights - Check adjustment
- High voltage cooling system - Check coolant level according to ElsaPro
- High voltage safety instruction labels - Check safety instruction labels for legibility
- High voltage system components - Check for damage and leaks; check cables and insulation for damage and proper mounting
- High voltage system maintenance connector- Check for damages (deformation and scratches) and connector cleanliness
- Horn - Check function
- Instrument cluster - Check warning and indicator lights
- Interior lights - Check all interior lights, trunk lights and glove box compartment illumination
- Motor compartment - Check transmission, final drive, and steering for leaks and damage (including visible HV components with front noise insulation removed)
- Multi-point inspection - Complete (USA only)
- Parking brake actuator - Check activating range with Vehicle Diagnostic Tester
- Plenum chamber and water drain valves - Check for dirt. NOTE: Time spent cleaning of item is a separate charge for service time.
- Road test - Perform

- Safety belts- Check function
- Service reminder indicator display - Reset display
- Space saver spare wheel and tire - Check condition and tire inflation pressure, adjust if necessary (if equipped)
- Sunroof systems - Check function (if equipped)
- Suspension and axle components (front and rear) - Check dust seals on ball joints and tie rod ends; check for excessive play
- Tire repair kit - Check and record the completeness and expiration date (if equipped)
- Tires - Check condition and tire tread wear; Check and record the tread depth
- Tires - Check tire inflation pressure and adjust if necessary
- Underbody - Check for damage and leaks, check the wheel well liners, underbody paneling and all lines are properly mounted
- Warning triangle - Check if present (if equipped)
- Windshield washer and headlight washing system - Add fluid if necessary; Check adjustment and function
- Wiper blades - Check condition and replace if necessary

- Safety belts- Check function
- Service reminder indicator display - Reset display
- Space saver spare wheel and tire - Check condition and tire inflation pressure, adjust if necessary (if equipped)
- Sunroof systems - Check function (if equipped)
- Suspension and axle components (front and rear) - Check dust seals on ball joints and tie rod ends; check for excessive play
- Tire repair kit - Check and record the completeness and expiration date (if equipped)
- Tires - Check condition and tire tread wear; Check and record the tread depth
- Tires - Check tire inflation pressure and adjust if necessary
- Underbody - Check for damage and leaks, check the wheel well liners, underbody paneling and all lines are properly mounted
- Warning triangle - Check if present (if equipped)
- Windshield washer and headlight washing system - Add fluid if necessary; Check adjustment and function
- Wiper blades - Check condition and replace if necessary

Odometer Check

Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

State Title Odometer Check
No issues reported

Auction Odometer Check
No issues reported

Odometer Calculation Check
No issues reported

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.
Vehicle: 2024 Audi Q8 Sportback e-tron quattro Prestige S-Line (WA1DAAGE9RB017929) **Report Run Date:** 11/04/2026 20:14:32 EST

2023 - Owner 1

Location: CT | **Owned From:** 08/2023 | **Usage:** Lease

Event Date	Location	Odometer	Data Source	Details
08/11/2023	STAMFORD, CT		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
09/16/2023	CT	25	Motor Vehicle Dept.	Title(Title #:AA5366390) (Leased Vehicle)
12/19/2023			Manufacturer	Manufacturer Recall Mfr. Recall 93U6 Safety Recall: CHARGING CABLE REPLACEMENT LOCATE YOUR NEAREST AUTHORIZED AUDI DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown
05/22/2024	CT	5,680	Service Record	Vehicle Inspected Electrical System Serviced
08/21/2024	CT	6,820	Service Record	Vehicle Inspected
12/13/2024	CT	10,500	Service Record	Vehicle Inspected Recommended Maintenance Performed Vehicle Detailed Wipers Replaced And/Or Serviced Electrical System Serviced Tires or Wheels Service Performed
02/10/2026	CT	19,320	Service Record	Vehicle Inspected Vehicle Detailed Electrical System Serviced
05/12/2026	CT	20,648	Service Record	Vehicle Inspected Vehicle Detailed

				Electrical System Serviced Tires or Wheels Service Performed
10/12/2026	EASTERN REGION	22,105	Auto Auction	Reported at Auto Auction
10/20/2026	EPHRATA, PA	22,105	Motor Vehicle Dept.	Title(Title #:90542455)

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to **AutoCheck Terms and Conditions**. If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (WA1DAAGE9RB017929) qualifies for **AutoCheck Buyback Protection.** If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbpterms or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.